





1. Lever tensions the 12" blade to 30,000 PSI (about twice that of ordinary frames).




2. Mount blade at 45° for flush cutting jobs.



3. Use frame as job saw (set screw holds blade in position).



4. Use as a compass saw with Hardflex® reciprocating blades.



5. Store spare blades inside tubular back.