Characteristics

Shear Strenath

Plastic Ranae

Melt Temperature (°F)

Re-melt Temperature (°F)

Flux Type Wetting Ability

Pre-cleaning of

Oxidized Copper

T 11 0: -1
Tensile Strength

Technical Information



Super-Set™

Up to 8,700 PSI

Up to 6.930 PSI

355°

355°

Controlled Flux Cored

Excellent

Not Required



**Ordinary Solder** 

7.500 PSI or Less

Required